

# CSI Country-Wide Case Study Safety Strategy Discussion

## Construction Safety Investigator



### Instructions:

---

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions typically pertain to all activities that workers will be involved in that may have the potential for safety related exposures. This case study is based on facts and materials developed and first published by the agency/organization identified in the section below entitled Source of Case Study Investigative Information.

#### Case Day:

September 2018

#### Accident Type:

Electrocution Accident – Interior Lighting Fixtures

#### Relevant Laws, Rules, and Codes May Include:

29CFR 1926.20(a)(1); 29 CFR 1926.20(b)(2); 29 CFR 1926.20(b)(4); 1926.20(f)(2); 1926.21; OAR 437-001-0760(7)(a); 29 CFR 1926.416(a)(3); 29 CFR 1926.416(a); 29 CFR 1926.417

- Oregon Administrative Rule
- National Electric Code

#### Case:

---

Newly hired lighting technician electrocuted while working night shift

#### Accident Detail:

---

A prime contractor had won a bid to replace fluorescent light fixtures with LED light fixtures in all 30+ stores of a national retail chain. The prime contractor then hired a staffing agency to contract lighting technicians to do the work.

The staffing agency (employer) who has been in business for approximately 30 years, recently acquired (5 months before incident) a small electrical contracting company based in California that was owned by a journeyman electrician. This was hired to be the technical manager of the staffing agency's new electrical contracting division and had 35+ years of experience as an electrician, and approximately 30+ years as a journeyman. In the staffing agency's employee handbook, the technical manager is listed as a "job site supervisor."

The acquired company had applied for and received a Construction Contractors Board license to operate in Oregon in 2015, but the license was not valid at the time of the incident. The staffing agency had been working in but was not licensed by the Construction Contractors Board to operate in Oregon at the time of the incident, did not have a valid Workers Compensation insurance policy, and was not licensed by the Electrical and Elevator Board with the Building Codes Division.

The decedent and the rest of the 6-person lighting technician crew had completed lighting fixture replacement in 11 stores in the 3 weeks prior to the incident.

At the time of the incident, the lighting technicians were replacing lights at another store location while the lighting circuits were energized.

Before work began in the store where the incident occurred, the foreman located what he thought was the lighting electrical panel, which was a 208/120V single-phase panel, but this panel was for accent lighting only. The main store lighting was in an uninspected panel and was a 480/277V 3-phase panel.

At the time of the incident, the decedent was working on a fixture without a quick disconnect. About 3:30am, co-workers noticed the decedent was slumped over the scaffold and not moving. CPR was initiated and co-workers called 911. The decedent was declared dead at the scene by EMS.

After the decedent was removed and law enforcement left, the foreman and remaining crew continued to work, completing the disconnect installation the decedent was working on, exposing themselves to similar, and potentially fatal, hazards.

### Reconstructive Safety Evaluation:

---

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?

### Agency's Accident Scene Conclusion:

---

- The decedent had been employed with a staffing agency for approximately 3 weeks, which, according to co-workers, was the extent of his experience in the electrical trade. This 3-week period served as his on-the-job training
- The technical manager, a journeyman electrician, who resided in California, did not inspect any stores in Oregon and the employer did not ensure a competent person was at the job site
- Some of the lighting systems in the stores had previously been retrofitted with quick disconnect circuits so that maintenance workers can replace fluorescent bulbs without having to turn off the circuit breaker to the lighting system. In the store where the incident occurred, about 60% of the light fixtures were not retrofitted with the quick disconnects. It was assumed that all stores were on the 120V single-phase circuits and previously retrofitted with luminaire (i.e., "quick") disconnects
- The employer had written policies on workplace safety for the mechanical and manufacturing divisions but did not develop workplace safety policies for the newly formed electrical division and did not assess the workplace safety policies of the newly acquired electrical contracting company that became the newly formed electrical division
- The employer had a written policy on de-energizing manufacturing equipment and installing lockout/tagout (LOTO) devices during machine repair and maintenance, but the recently acquired company had no written policy for de-energizing lighting circuits or for installing LOTO devices on electrical systems
- Lighting technicians were not trained in LOTO procedures and were not provided LOTO devices to lockout an electrical system
- Lighting technicians were not evaluated for workplace safety knowledge or practice, nor did they receive safety training or direction from either the employer or the technical manager. Thus, employees were not aware of any company policies, or dangers of working on energized circuits
- The employer and the technical manager of the newly formed electrical division were unable to produce any documentation of workplace safety training for any lighting technician. This included a lack of documentation of any assessment or training provided to the decedent during his tenure with the employer
- The technical manager stated he was not surprised the foreman did not locate the correct electrical panel as he probably did not know what he was looking for. These comments by the technical manager suggest that supervision and training was inadequate for the foreman and his crew



## Chubb. Insured.<sup>SM</sup>

This document is designed to be used as part of an overall construction or renovation site loss prevention program. It may be used as a resource in helping identify conditions that potentially create risks and exposures for property damage and bodily injury. Remediation, adjustment, or improvement in any of these conditions is the sole responsibility of the owner, developer, or contractor.

Chubb is the marketing name used to refer to subsidiaries of Chubb Limited providing insurance and related services. For a list of these subsidiaries, please visit our website at [www.chubb.com](http://www.chubb.com). Insurance provided by ACE American Insurance Company and its U.S.-based Chubb underwriting company affiliates. All products may not be available in all states. This communication contains product summaries only. Coverage is subject to the language of the policies as actually issued. This document is advisory in nature and is offered for informational purposes only as a resource to be used together with your professional insurance advisors in maintaining a loss prevention program. The information contained in this document is not intended as a substitute for legal, technical, or other professional advice. Chubb, 202 Hall's Mill Road, Whitehouse Station, NJ 08889-1600.